



Sanitary Sewer Overflow Annual Report

Division of Surface Water

Date: MARCH 1, 2021
Facility name: WILLOUGHBY-EASTLAKE WATER POLLUTION CONTROL CENTER
Ohio NPDES permit no.: 3PD00024*TD
Period covered by report: JANUARY 1, 2020 to DECEMBER 31, 2020

Contact person

Name: JOHN A. GORKA
Title: SUPERINTENDENT WW4-1013603-91
Mailing address: 221 ERIE ROAD, EASTLAKE, OH 44095
Telephone: (440)953 - 4186
Email: jgorka@willoughbyohio.com

Certification:

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name JOHN A. GORKA WW4-1013603-91 **Title:** SUPERINTENDENT
(typed): _____

Signature: _____ **Date:** _____

Enter narrative analysis of WIB patterns by location, frequency and cause.

| | | |
|---------------------------------------|---|---|
| Kirtland Road - Willoughby | D | House call for water in basement. Sanitary main blocked due to build up of of toilet paper. Jetted down stream manhole relieved blockage. |
| Crossbrook/Tamarac Blvd. - Willoughby | D | Down stream manhole was surcharged, and went to next manhole within Tamarac apartments and jetted line. Back up relieved within 25 minutes of initial call. |